

IDC5 software update

**CAR 65.0.0**

**TEXA**

# IDC5 software update CAR 65.0.0

The new software update **CAR 65** offers the best of the multi-brand diagnosis by TEXA: a large number of diagnostic developments, special functions and technical information that is essential in order to complete even the most complex workshop operations successfully.

IDC5 CAR 65 includes **over 32,000 new possible selections** for the major makes on the market worldwide, among which: **ABARTH, ALFA ROMEO, ASTON MARTIN, BENTLEY, BMW, CHRYSLER, DODGE, FERRARI, FIAT, FORD, HONDA, INFINITI, JAGUAR, JEEP, LAMBORGHINI, LAND ROVER, LEXUS, MASERATI, MERCEDES-BENZ, MINI, NISSAN, PORSCHE, ROLLS-ROYCE, SUBARU, TOYOTA, VOLKSWAGEN, VOLVO.**

**55 makes and 1091 models** belonging to the CAR and SUPERCAR categories have been updated.

**Over 200 systems** are involved in this update; **1500 diagnostic systems** have been released.

Following is a brief overview of all the new features contained in the CAR 65 version:

## New SUPERCAR features divided by system

### ABS

**PORSCHE:** Boxster [08>11] (987) Spyder 3.4i S 24v Kat; Cayenne [10>] (92A/958) Diesel 3.0 V6 TDI; Cayenne [10>] (92A/958) S Hybrid 3.0i V6 Kat Hybrid; Cayenne [14>] (92A/958) S E-Hybrid 3 . 0 i V6 Kat Plug-in Hybrid.

**ROLLS-ROYCE:** Ghost [09>] (RR4) 6.6i V12 Biturbo Kat.

### AIRBAG

**ASTON MARTIN:** DBS [07>12] Coupé 5.9i V12 Kat; DBS [09>12] Volante 5.9i V12 Kat; Rapide [10>13] 5.9i V12 Kat; Rapide S [13>] 5.9i V12 Kat; Vantage [05>] Coupé 4.3i V8 Kat.

**BENTLEY:** Bentayga [15>] 6.0i W12 Kat; Bentayga [16>] Diesel 4.0 V8 TD; Continental [11>] GT 6.0i W12 Biturbo Kat; Continental [11>] GT Speed 6.0i W12

In addition to this data, it is important to highlight the great work that has been done for the diagnosis and calibration of the Driver assistance systems and of the ADAS.

As far as the latter are concerned, starting from version 65, at the end of the calibration procedures it will be possible to print the results to hand over to the customer. Another new feature is the **IR Calibration Target**, a new tool to be used in combination with the Mercedes panel for the calibration of the night vision systems on models S, SL, CLS, E.

NOTE: IDC5 software not available for the old generation tools AXONE Direct, AXONE Pad, AXONE Palmtop.

Biturbo Kat; Continental [12>] GTC Speed 6.0i W12 Biturbo Kat; Continental [13>] GT V8 4.0i V8 Biturbo Kat; Flying Spur [13>] 4.0i V8 Biturbo Kat; Flying Spur [13>] 6.0i W12 Biturbo Kat.

**PORSCHE:** Boxster [08>11] (987) Spyder 3.4i S 24v Kat.

### Park assist

**BENTLEY:** Mulsanne [11>] 6.8i V8 Kat.

**PORSCHE:** Boxster [08>11] (987) Spyder 3.4i S 24v Kat; Cayenne [10>] (92A/958) Diesel 3.0 V6 TDI; Cayenne [14>] (92A/958) S E-Hybrid 3.0i V6 Kat Plug-in Hybrid; Cayenne [14>] (92A/958) S E-Hybrid 3.0i V6 Kat Plug-in Hybrid.

**ROLLS-ROYCE:** Ghost [09>] (RR4) 6.6i V12 Biturbo Kat.

## Automatic transmission

**ASTON MARTIN:** Vantage [05>] Coupé 4.3i V8 Kat; Vantage [07>] Roadster 4.3i V8 Kat.

**LAMBORGHINI:** Huracan [14>] LP 610-4 5.2i V10 Kat; Huracan [16>] LP 580-2 5.2i V10 Kat; Huracan [16>] LP 610-4 Spyder 5.2i V10 Kat.

**PORSCHE:** Boxster [08>11] (987) Spyder 3.4i S 24v Kat.

## Driving dynamics control

**PORSCHE:** Cayenne [10>] (92A/958) Diesel 3.0 V6 TDI; Cayenne [10>] (92A/958) S Hybrid 3.0i V6 Kat Hybrid; Cayenne [14>] (92A/958) S E-Hybrid 3.0i V6 Kat Plug-in Hybrid.

**ROLLS-ROYCE:** Ghost [09>] (RR4) 6.6i V12 Biturbo Kat.

## Distance control

**BENTLEY:** Bentayga [15>] 6.0i W12 Kat; Bentayga [16>] Diesel 4.0 V8 TD.

## Radiator figure control

**ROLLS-ROYCE:** Phantom [03>12] (RR1) 6.750i V12 Kat; Phantom [05>12] (RR1) L 6.750i V12 Kat; Phantom [07>] (RR2) Drophead 6.750i V12 Kat; Phantom [08>] (RR3) Coupé 6.750i V12 Kat.

## Instrumentation

**FERRARI:** 430 [07>09] (F131) Scuderia 4.3i V8 32v Kat; 488 [15>] (F142M) GTB 3.9i V8 Kat; 488 [15>] (F142M) Spider 3.9i V8 Kat; F430 [05>09] (F131) Spider 4.3i V8 32v Kat.

# New CAR features divided by system

## Park assist

**ABARTH:** 500 | BR 1.4i 16v MultiAir Turbo Kat.

**ALFA ROMEO:** Mito [08>] (955) 1.3 16v JTDm-2.

**BMW:** 3 [98>06] (E46) Coupé 320 Cd; 3 [98>06] (E46) Coupé 330 Cd.

**CHEVROLET:** Aveo [11>] (T300) Sedan 1.4i 16v Kat; Spark [16>] (M400) 1.4i 16v Kat; PT Cruiser [01>10] Cabrio 2.4i 16v Kat

**CITROËN:** C 4 [10>] (B7) 1.6 8v e-HDI.

**DODGE:** Journey | BR 3.6i V6 Kat.

**FIAT:** 500 [07>] (312) 0.9i 8v TwinAir Kat.

**FORD:** Kuga [17>] (DM2) Facelift 2.0 16v TDCi 4x4

**HONDA:** Civic | BR 1.5i Turbo Kat; Civic X [17>] (FC) Hatchback 1.0i 12v Turbo Kat.

**HYUNDAI:** Elantra [16>] (AD) 1.6i 16v Turbo GDi Kat.

**JEEP:** Renegade [14>] (BU) 1.4i 16v Turbo Kat GPL.

And many more.

## High beam assist

**AUDI:** R8 [15>] (4S3) Coupé 5.2i V10 FSI quattro; R8 [16>] (4S9) Spyder 5.2i V10 FSI quattro; S4 [16>] (8W2) 3.0i V6 TFSI Kat quattro; S4 [16>] (8W5) Avant 3.0i V6 TFSI Kat quattro; S5 [16>] (F53) Coupé 3.0i V6 TFSI Kat quattro; S5 [16>] (F57) Cabrio 3.0i V6

TFSI Kat quattro; S5 [16>] (F5A) Sportback 3.0i V6 TFSI Kat quattro.

**BMW:** Z4 [09>16] (E89) 1.8si Kat; Z4 [09>16] (E89) 2.0si Kat; Z4 [09>16] (E89) 3.5si Kat.

**PEUGEOT:** 508 [11>] (W2) Break 2.0i 16v Kat.

**SEAT:** Toledo [12>] (KG3) 1.2i 12v Kat.

**SKODA:** Fabia [15>] (NJ) Kombi 1.6i 16v Kat; Kodiaq [17>] (NS7) 1.4i 16v TSI Kat.

**VOLKSWAGEN:** Touran [15>] (5T) 1.8i 16v TSI Kat; Touran [15>] (5T) 1.8i 16v TSI Kat; Vento [10>] (162) 1.4i 16v TSI Kat.

## Lane change assist

**FORD:** Edge | BR 3.5i V6 Kat; Edge | BR 3.5i V6 Kat 4x4; Fusion | BR 2.0i 16v Kat Ecoboost; Ranger | BR 2.2 16v TDCi; Ranger | BR 2.5i 16v Flex Kat; Ranger | BR 3.2 20v TDCi; Galaxy [15>] 1.5i 16v Kat Ecoboost; S-Max [15>] 2.0i 16v Kat Ecoboost; Tourneo Connect [13>] 1.0i 12v Kat Ecoboost.

**SEAT:** Leon [05>12] (1P1) 1.4i 16v Kat; Leon [05>12] (1P1) 1.8i 16v TSI Kat; Leon [05>12] (1P1) 2.0 16v TDI

**VOLKSWAGEN:** Touareg [10>] (7P5) 3.0 V6 TDI 4Motion; Vento [10>] (162) 1.4i 16v TSI Kat; Vento [10>] (162) 1.4i 16v TSI Kat; Vento [10>] (162) 1.4i

16v TSI Kat.

## Lane change assist

**AUDI:** A5 [16>] (F53) Coupé 1.4i 16v TFSI Kat; A5 [16>] (F5A) Sportback 1.4i 16v TFSI Kat; SQ5 [17>] (FY) 3.0i V6 TFSI Kat Quattro.

**BMW:** 2 [14>] (F22) 218 d; 4 [14>] (F32) Coupé 418i Kat; 4 [14>] (F32) Coupé 420 d; X4 [14>] (F26) M 40i Kat; X5 [13>] (F15) 25 sd.

**FIAT:** 500X [15>] (334) 1.4i 16v Turbo Kat GPL; 500X [15>] (334) 2.4i 16v MultiAir2 Kat.

**JEEP:** Renegade [14>] (BU) 1.4i 16v Turbo Kat GPL; Renegade [14>] (BU) 1.6 16v MJ

**MERCEDES-BENZ:** G [93>] (463) T 350 D BlueTEC.

**SKODA:** Kodiaq [17>] (NS7) 2.0i 16v TSI Kat 4x4

**TOYOTA:** C-HR [17>] (NG/ZY) 1.2i 16v Turbo Kat; C-HR [17>] (NG/ZY) 1.8i VVT-i HSD Kat; C-HR [17>] (NG/ZY) 2.0i 16v Kat.

## Lane keeping assist

**AUDI:** A6 [05>11] (4FH) Avant Allroad 3.0i V6 24v TFSI Kat quattro; A6 [05>11] (4FH) Avant Allroad 3.2i V6 FSI Kat quattro; A6 [05>11] (4FH) Avant Allroad 4.2i V8 FSI Kat quattro; RS6 [08>12] (4F2) 5.0i V10 TFSI Kat quattro; S6 [06>11] (4F2) 5.2i V10 FSI Kat quattro; S6 [06>11] (4F5) Avant 5.2i V10 FSI Kat quattro

**VOLKSWAGEN:** Passat B7 [10>14] (365) Variant 2.0i 16v TSI Kat; Passat B7 [10>14] (365) Variant 3.6i VR6 FSI Kat; Passat CC [12>] (358) Facelift 3.6i V6 FSI Kat.

## Lane departure warning

**CITROËN:** C 4 [10>] (B7) 1.2i 12v THP Kat; C 4 [10>] (B7) 1.6 8v e-HDI; C 5 [08>] (X7) 2.0 16v HDI; C 5 [08>] (X7) Break 2.0 16v HDI; DS4 [11>] (B75) 1.2i 12v THP Kat.

## Hybrid battery

**MERCEDES-BENZ:** E [09>15] (212) 300 CDI BlueTEC Hybrid; E [09>15] (212) 400i Kat Hybrid; E [09>16] (212) T300 CDI BlueTEC Hybrid; E [11>16] (212) L 400i Kat Hybrid; ML/GLE [11>] (166) 500e Kat 4 Matic Plug-in hybrid.

**MITSUBISHI:** Minicab MiEV [12>] (U67/U68) electric.

## Obstacle detection control unit, right and left sides

**FORD:** Mondeo V [15>] 1.5 8v TDCi; Mondeo V [15>] 1.5 8v TDCi ECOnetic; Mondeo V [15>] Turnier 2.0i 16v Kat Ecoboost.

**JAGUAR:** XF [08>15] (X250) 2.0i 16v Turbo Kat; XF [08>15] (X250) 2.2 16v D; XF [12>15] (X250) Sportbrake 3.0 V6 D; XF-R [09>15] (X250) 5.0i V8 Kat; XF-S [08>15] (X250) 3.0 V6 D; XF-S [12>15] (X250) Sportbrake 3.0 V6 D.

## Distance control

**AUDI:** A5 [16>] (F53) Coupé 1.4i 16v TFSI Kat; A5 [16>] (F5A) Sportback 1.4i 16v TFSI Kat; SQ5 [17>] (FY) 3.0i V6 TFSI Kat Quattro.

**FORD:** Fiesta | BR 1.6i 16v Flex Kat; B-Max [12>] (JK) 1.0i 12v Kat Ecoboost; C-Max [15>] (DXA) Facelift 1.5 8v TDCi; Focus [15>] (DYB) Facelift 1.5 8v TDCi ECOnetic; Kuga [17>] (DM2) Facelift 2.0 16v TDCi 4x4.

**PEUGEOT:** 3008 [09>16] (T84) 2.0i 16v Kat.

**SKODA:** Kodiaq [17>] (NS7) 1.4i 16v TSI Kat.

**SUZUKI:** Baleno [16>] (A1K) 1.2i 16v Kat Hybrid; SX4 S-Cross | BR 1.6i 16v Kat.

## Right and left blind spot module

**ACURA:** CSX [06>11] (FD) 2.0i 16v Kat; ILX [13>] (DE) 1.5i 16v Kat Hybrid; MDX [01>13] (YD) 3.5i V6 Kat; RLX [13>] (KC) 3.5i V6 Kat; RSX [02>10] (DC) 2.0i 16v Kat.

**ALFA ROMEO:** Giulia [16>] (952) 2.0i 16v Turbo MultiAir Kat; Giulia [16>] (952) 2.0i 16v Turbo MultiAir Kat Q4 Veloce.

**FIAT:** 500X [15>] (334) 2.4i 16v MultiAir2 Kat

**HONDA:** Accord VIII [08>15] (CU) Sedan 2.0i 16v Kat; Airwave [05>10] (GJ) 1.5i 16v Kat 4WD; Amaze [13>] 1.2i 16v V-TEC Kat; Ballade [11>] 1.5i 16v V-TEC Kat; Brio [11>] 1.2i 16v V-TEC Kat; Civic VIII [06>12] (FK/FN) Hatchback 1.4i 16v V-TEC Kat.

**KIA:** Optima IV [16>] (JF) Plug-in Hybrid 2.0i 16v GDi Kat; Optima IV [16>] (JF) Sportswagon 1.6i 16v Turbo GDi Kat; Sportage [16>] (QL) 2.4i 16v GDi Kat.

**SUBARU:** Levorg [14>] (VM/V10) 1.6i 16v Turbo Kat 4WD; Levorg [14>] (VM/V10) 1.6i 16v Turbo Kat 4WD.

## Pre-crash system

**FIAT:** Panda [12>] (319) 1.3 MJ 16v 4x4

**HONDA:** Civic | BR 1.5i Turbo Kat; Civic X [17>] (FC) Hatchback 1.0i 12v Turbo Kat; Civic X [17>] (FC) Hatchback 1.5i 16v Turbo Kat; Civic X [17>] (FC) Hatchback 2.0i 16v Type R Kat; CR-V [12>] (RM) 1.6

16v i-DTEC CR-V | BR 2.4i Kat

**KIA:** Niro [17>] 1.6i 16v GDi Kat Hybrid

And many more.

# List of new Special Functions, European market

## Park assist

**AUDI:** A6 [11>] (4G2); A6 [11>] (4G5) Avant; A6 [13>] (4GH) Avant Allroad; A7 [10>] (4GA) Sportback; A8 [10>] (4H2); A8 [11>] (4H8) L; A8 [14>] (4HC); A8 [14>] (4HL) L; RS6 [13>] (4G5) Avant; RS7 [13>] (4GA) Sportback; S6 [12>] (4G2); S6 [12>] (4G5) Avant; S7 [10>] (4GA) Sportback; S8 [12>] (4H2); S8 [14>] (4HC);

**BENTLEY:** Mulsanne [11>];

**RENAULT:** Espace V [15>] (XFC/JR); Kadjar [15>] (XFE); Megane IV [16>] (B9A); Megane IV [16>] (K9A) Grandtour; Scenic IV [16>]; Talisman [15>]; Talisman [16>] Grandtour;

**RENAULT SAMSUNG:** SM6 [16>]

## Driver assistance

**AUDI:** A4 [15>] (8W2); A4 [15>] (8W5) Avant; A4 [16>] (8WH) Avant Allroad; A5 [16>] (F53) Coupé; A5 [16>] (F57) Cabrio; A5 [16>] (F5A) Sportback; A6 [11>] (4G2); A6 [11>] (4G5) Avant; A6 [13>] (4GH) Avant Allroad; A7 [10>] (4GA) Sportback; A8 [10>] (4H2); A8 [11>] (4H8) L; A8 [14>] (4HC); A8 [14>] (4HL) L; Q5 [17>] (FY); Q7 [15>] (4MB); R8 [15>] (4S3) Coupé;

**BENTLEY:** Bentayga [15>]; Bentayga [16>] Diesel;

**CITROËN:** SpaceTourer [16>] (K0);

**DACIA:** Duster [13>] (HS) Facelift;

**FORD:** Kuga [13>] (DM2);

**HYUNDAI:** Elantra [16>] (AD); Ioniq [17>]; Ioniq [17>] EV; Sonata VII [15>] (LF);

**KIA:** Niro [17>]; Optima IV [16>] (JF); Optima IV [16>] (JF) Plug-in Hybrid; Optima IV [16>] (JF) Sportswagon; Sportage [16>] (QL);

**NISSAN:** Micra [17>] (K14); X-Trail [14>] (T32);

## Camera and radar calibration

**CITROËN:** SpaceTourer [16>] (K0);

**FORD:** Kuga [13>] (DM2);

**HYUNDAI:** Ioniq [17>]; Ioniq [17>] EV; Sonata VII [15>] (LF);

**KIA:** Niro [17>]; Optima IV [16>] (JF); Optima IV [16>] (JF) Plug-in Hybrid; Optima IV [16>] (JF) Sportswagon; Sportage [16>] (QL);

**MERCEDES-BENZ:** SL (231), E (207), E (212), CLS (218), S (222), S (217).

**PEUGEOT:** 3008 [16>] (P84); 308 [13>] (T9); 308 [14>] (T9) Station Wagon; 5008 [17>] (P87); Traveller [16>] (K0);

**SUBARU:** Levorg [14>] (VM/V10);

**VOLVO:** S90 II [16>]; V90 II [16>]; XC90 II [15>].

## FAST-FIT

**CHANGAN:** Alsvin V7 [14>]; Benben [07>]; Benben Love [10>]; Benben Mini [10>]; CS35 [12>]; CS75 [14>]; CX20 [10>]; Eado [14>]; Raeton [13>]; Star [12>];

**CHEVROLET:** Beat [10>] (M300); Captiva [11>] (C140); Matiz [04>07] (M200); Matiz [07>10] (M250); Spark [09>15] (M300); Volt [11>];

**MINI:** Mini (F55/F56) [14>] Cooper; Mini (F55/F56) [14>] Cooper S; Mini (F55/F56) [15>] John Cooper Works;

**MITSUBISHI:** ASX [10>] (GA); Galant Fortis [07>] (CY/CZ); Galant Fortis Sportback [09>] (CX); Lancer [08>] (CY/CZ); Lancer [08>] (CY/CZ) Hatchback; Lancer Sportback [08>] (CX); Montero [06>] (V80/V90); Outlander [07>14] (CW); Outlander [12>] (GF); Outlander PHEV [13>] (GG); Pajero [06>] (V80/V90);

Shogun [06>] (V80/V90);

**NISSAN:** Micra [17>] (K14); Note [06>12] (E11); X-Trail [14>] (T32);

**OPEL (GM):** Ampera [12>]; Antara [11>];

**PEUGEOT:** 3008 [16>] (P84); 307 [05>09] (T6); 307 [05>09] (T6) CC; 307 [05>09] (T6) Station Wagon; 308 [07>13] (T7); 308 [08>13] (T7) Station Wagon; 308 [13>] (T9); 308 [14>] (T9) Station Wagon; 407 [04>11] (D2); 407 [04>11] (D2) Break; 407 [05>11] (D2) Coupé; 408 [10>14] (T73); 5008 [17>] (P87); RCZ [10>] (T75); Traveller [16>] (K0);

**RAVON:** R2 [15>];

**SEAT:** Altea [04>15] (5P1); Altea Freetrack [07>15] (5P8); Altea XL [06>15] (5P5); Toledo [04>10] (5P2);

**SKODA:** Kodiaq [17>] (NS7); Octavia [13>] (5E3); Octavia [13>] (5E5) Kombi; Superb [09>15] (374); Yeti [09>] (5L7);

**SUZUKI:** Splash [08>] (A5B); SX4 [06>14] (RW);

**VOLVO:** C30 [06>13]; C70 Cabrio II [06>13]; S40 [04>12] Facelift; V50 [04>12]; XC90 I [03>14];

**WULING:** Sunshine [02>].

## Tyre pressure

**DODGE:** Journey [11>] (JC); Journey | BR

**HYUNDAI:** Creta [15>] (GS/GSR)

**OPEL (GM):** Ampera EV [17>]

**RAVON:** R4 [16>]

**RENAULT:** Koleos II [17>]; Talisman [15>]; Talisman [16>] Grandtour

**RENAULT SAMSUNG:** QM6 [17>]; SM6 [16>].

# List of new DASHBOARD\* features divided by system

## ABS

**ABARTH:** 500 | BR; Punto | BR; 124 Spider [16>] (348); 500 [08>] (312); 500C [10>] (312); Punto [07>12] (199); Punto [10>] (199) Evo; Punto [12>] (199);

**ACURA:** CL [96>03] (YA); CSX [06>11] (FD); EL [96>05] (MB/ES); ILX [13>] (DE); MDX [01>13] (YD); MDX [14>] (YD); RDX [06>12] (TB); RDX [13>] (TB); RL [96>04] (KA); RL [04>12] (KB); RLX [13>] (KC); RSX [02>10] (DC); TL [95>09] (UA); TL [09>13] (UA);

## Transportation mode programming

**BMW:** 5 [17>] (G30); 5 [17>] (G31) Touring; 7 [15>] (G11); 7 [15>] (G12);

**RENAULT:** Megane IV [16>] (B9A); Megane IV [16>] (K9A) Grandtour;

## Particulate filter regeneration

**DACIA:** Duster [13>] (HS) Facelift;

**HYUNDAI:** H1 [08>] (TQ);

**MITSUBISHI:** ASX [10>] (GA);

**NISSAN:** Micra [17>] (K14); X-Trail [14>] (T32);

**RENAULT:** Captur [13>] (X87/J5); Megane IV [16>] (B9A); Megane IV [16>] (K9A) Grandtour; Talisman [15>]; Talisman [16>] Grandtour;

**RENAULT SAMSUNG:** QM3 [13>]; SM6 [16>];

**SKODA:** Yeti [09>] (5L7);

## Brake pad replacement

**FERRARI:** 488 [15>] (F142M) GTB; 488 [15>] (F142M) Spider;

**KIA:** Optima IV [16>] (JF); Optima IV [16>] (JF) Plug-in Hybrid; Optima IV [16>] (JF) Sportswagon; Sorento III [15>] (UM);

**MITSUBISHI:** Outlander [12>] (GF); Outlander PHEV [13>] (GG);

## TPMS

**MASERATI:** GranTurismo [07>] (M145); GranTurismo [10>] (M145) Convertible; Quattroporte [07>12] (M139 EV07).

TLX [14>] (UB); TSX [03>08] (CL); TSX [09>14] (CU); ZDX [10>13] (YB);

**ALFA ROMEO:** 147 [00>10]; 156 [97>05]; 156 [97>05] Sport Wagon; 166 [98>08]; Giulia [16>] (952); Giulietta [10>] (940); GT [03>10]; Mito [08>] (955);

**ASTON MARTIN:** DB9 [04>12] Coupé; DB9 [04>12] Volante; Vantage [05>] Coupé; Vantage [07>] Roadster;

**BMW:** 3 | BR; 5 | BR; 7 | BR; 8 | BR; 1 [04>11] (E87);

1 [07>11] (E81); 1 [07>12] (E82) Coupé; 1 [08>12] (E88) Cabrio; 3 [90>99] (E36); 3 [90>99] (E36) Coupé; 3 [93>01] (E36) Compact; 3 [93>99] (E36) Cabrio; 3 [94>00] (E36) Touring; 3 [98>05] (E46); 3 [98>05] (E46) Touring; 3 [98>06] (E46) Coupé; 3 [99>07] (E46) Cabrio; 3 [01>04] (E46) Compact; 3 [05>11] (E90); 3 [05>12] (E91) Touring; 3 [06>13] (E92) Coupé; 3 [07>13] (E93) Cabrio;

**CHEVROLET:** Astra | BR; Corsa | BR; Omega | BR; Vectra | BR; Zafira | BR; Corsa II [02>12];

**DACIA:** Logan [07>12] Pick-Up; Logan [04>12] (LS); Logan [06>12] (KS) MCV; Logan [07>12] (US) Pick-Up; Sandero [08>12] (BS); Sandero [08>12] (BS) Stepway; Solenza [03>05];

**FERRARI:** 430 [07>09] (F131) Scuderia; 599 GTB Fiorano [06>12] (F141); 599 GTO [10>12] (F141); 612 Scaglietti [04>07] (F137); 612 Scaglietti [07>11] (F137 MY); F430 [05>09] (F131); F430 [05>09] (F131) Spider; F430 [07>09] (F131) Challenge; Scuderia [08>09] (F131) Spider 16M;

**FORD:** Ka [08>16] (RU8);

**HONDA:** Accord | BR; City | BR; Civic | BR; CR-V | BR; Fit | BR; HR-V | BR; Odyssey | BR; Pilot | BR; Prelude | BR; Accord VI [97>03] (CG) Coupé; Accord VI [98>03] (CG) Hatchback; Accord VI [98>03] (CG) Sedan; Accord VII [03>08] (CL) Sedan; Accord VII [03>08] (CL) Tourer; Accord VIII [08>15] (CU) Sedan; Accord VIII [08>15] (CU) Tourer; Accord IX [15>] (CR) Coupé; Accord IX [15>] (CR) Sedan; Acty Van [99>]; Airwave [05>10] (GJ); Amaze [13>]; Ascot [94>97] (CE); Avancier [00>03] (TA); Ballade [11>]; Brio [11>]; Capa [98>02] (GA); City III [98>02]; City IV [02>08]; City V [08>]; City VI [13>]; Civic [95>00] Fastback; Civic [99>01] Aerodeck; Civic [00>05] (ES) Hybrid; Civic [00>05] (EU) Hatchback; Civic [00>05] (EU) Sedan; Civic [01>05] (EM) Coupé; Civic [03>05] (ET) Sedan;

**JEEP:** Renegade [14>] (BU);

**KIA:** Cerato | BR; Opirus | BR; Rio | BR; Sportage | BR; Amanti [03>10] (GH); Carens II [02>06] (FJ); Carnival II [01>06] (GQ); Cerato [04>09] (LD); Clarus II [98>00] (FE); Joice [99>03] (NO); Magentis [00>06] (MS/GD); Opirus [03>10] (LD/GH); Rio [00>05] (BC/DC); Rio [02>05] (BC/DC) Kombi; Sportage [93>04] (AL/JA); Visto [99>04];

**LADA:** Largus [12>];

**LANCIA:** Delta [08>13] (181); Musa [04>]; Phedra [02>10]; Ypsilon [11>];

**LAND ROVER:** Discovery III [04>09] (TA); Range Rover Sport I [05>09] (LS);

**MASERATI:** Quattroporte [04>07] (M139); Quattroporte [07>12] (M139 EV07);

**MAZDA:** Mazda3 [14>] (BM); Mazda3 [14>] (BM) Sedan; Mazda6 [14>] (GJ); Mazda6 [14>] (GJ) Station Wagon;

**MERCEDES-BENZ:** C | BR; C [07>14] (204); C [07>14] (204) T; C [14>] (205); C [14>] (205) L; C [14>] (205) T; C [15>] (205) Coupé; C [16>] (205) Cabrio; CL [06>15] (216); GL [06>12] (164); GLC [15>] (253); GLC [16>] (253) Coupé; GLK [08>15] (204); ML [05>11] (164); R [06>13] (251); R [06>13] (251) L; S [05>13] (221); S [05>13] (221) L; S [13>] (222); S [13>] (222) L; S [14>] (217) Coupé; S [15>] (217) Cabrio; S [15>] (222) Maybach;

**MITSUBISHI:** i-MiEV [11>] (HA);

**NISSAN:** Kubistar (X76);

**OPEL (GM):** Astra-G [00>05] Cabrio; Astra-G [97>05]; Astra-G [97>05] Coupé; Astra-G [97>05] Station Wagon; Corsa-C [00>07]; Corsa-C [05>07] Van; Corsa-D [07>14]; Corsa-D [08>14] Van; Meriva-A [03>10]; Omega-B [94>03]; Vectra-B [95>02]; Vectra-B [95>03] Station Wagon; Zafira-A [99>05];

**PORSCHE:** 911 [97>04] (996) Carrera; 911 [98>04] (996) Carrera 4; 911 [99>04] (996T) GT3; 911 [99>04] (996T) Turbo; 911 [01>04] (996) Coupé; 911 [01>04] (996T) GT2; Boxster [96>04] (986); Carrera [04>06] GT;

## AIRBAG

**ASTON MARTIN:** DB9 [04>12] Coupé; DB9 [04>12] Volante; DBS [07>12] Coupé; DBS [09>12] Volante; Rapide [10>13]; Rapide S [13>]; Vantage [05>] Coupé; Vantage [07>] Roadster;

**AUDI:** A1 | BR; A3 | BR; A4 | BR; A1 [11>] (8X1/8XF); A1 [12>] (8XA/8XK) Sportback; A3 [03>13] (8P1); A3 [03>13] (8PA) Sportback; A3 [08>14] (8P7) Cabrio; A3 [12>] (8V1); A3 [12>] (8VA) Sportback; A3 [14>] (8V7) Cabrio; A3 [14>] (8VS) Sedan; A4 [07>15] (8K2); A4 [07>15] (8K5) Avant; A4 [09>15] (8KH) Avant Allroad; A5 [07>16] (8T3) Coupé; A5 [09>16] (8F7) Cabrio;

A5 [09>16] (8TA) Sportback; A6 [04>11] (4F2); A6 [04>11] (4F5) Avant; A6 [05>11] (4FH) Avant Allroad; A6 [11>] (4G2);

**LANCIA:** Musa [04>]; Ypsilon [06>11];

**MERCEDES-BENZ:** C [14>] (205); C [14>] (205) L; C [14>] (205) T; C [15>] (205) Coupé; C [16>] (205) Cabrio; GLC [15>] (253); GLC [16>] (253) Coupé; S [13>] (222); S [13>] (222) L; S [14>] (217) Coupé; S [15>] (217) Cabrio; S [15>] (222) Maybach;

## Park assist

**ABARTH:** 500 | BR; 500 [08>] (312); 500C [10>] (312);

**ALFA ROMEO:** 4C [13>]; Giulia [16>] (952);

**FIAT:** 500 | BR; 500 [07>] (312); 500C [09>] (312); 500L [12>] (330); 500L [13>] (334) Living; Panda [12>] (319); Panda [14>] (319) Cross; Tipo [15>] (356);

## Lane change assist

**LEXUS:** RX 350 | BR; ES (V6) 200 [16>]; ES (V6) 250 [12>]; ES (V6) 300h [12>]; ES (V6) 350 [12>]; GS (L1) 300h [13>]; GS (L1) 350 [12>]; GS (L1) 450h [12>]; GS (L1) F [15>]; IS (E3) 200t [15>] Sedan; IS (E3) 250 [13>15] Sedan; IS (E3) 300 [16>] Sedan; IS (E3) 300h [13>] Sedan; IS (E3) 350 [13>] Sedan; LX (J2) 450d [16>]; LX (J2) 570 [15>]; NX (Z1) 200t [14>]; NX (Z1) 300h [14>]; RC (C1) 200t [15>]; RC (C1) 300h [15>];

**TOYOTA:** Hi-Lux | BR; Prius | BR; Aurion [12>] (V50); Avalon IV [12>] (X40); Avalon IV [13>] (X40) Hybrid; Camry [12>] (V5); Camry [12>] (V5) Hybrid; Fortuner [16>]; Highlander III [14>] (U5); Highlander III [14>] (U5) Hybrid; Hi-Lux [16>] Pick-Up; Hi-Lux [16>] SW4; Land Cruiser [07>] (J20); Mirai [15>] (D10); Prius [16>] (ZVW); Prius + (alpha) [11>] (W40); Prius Prime [17>] (ZVW) Plug-in; RAV4 [13>] (A4);

## Air conditioning

**ABARTH:** 500 | BR; Punto | BR; 500 [08>] (312); 500C [10>] (312); Punto [07>12] (199); Punto [10>] (199) Evo;

**ALFA ROMEO:** 8C [07>09]; 8C [08>10] Spider; Giulia [16>] (952); Mito [08>] (955);

**MASERATI:** GranTurismo [07>] (M145); GranTurismo [10>] (M145) Convertible;

**MERCEDES-BENZ:** A [04>12] (169); A [04>12] (169) Coupé; B [05>11] (245); C [14>] (205); C [14>] (205)

L; C [14>] (205) T; C [15>] (205) Coupé; C [16>] (205) Cabrio; E [16>] (213); E [16>] (213) L; E [16>] (213) T; E [17>] (238) Cabrio; E [17>] (238) Coupé; GLC [15>] (253); GLC [16>] (253) Coupé; S [13>] (222); S [13>] (222) L; S [14>] (217) Coupé; S [15>] (217) Cabrio; S [15>] (222) Maybach;

**SEAT:** Ateca [16>] (KH); Ibiza [15>] (6P1) Sportcoupé; Ibiza [15>] (6P5); Ibiza [15>] (6P8) ST; Leon [12>] (5F1); Leon [12>] (5F5) SC; Leon [14>] (5F8) ST; Toledo [12>] (KG3);

**SKODA:** Fabia [15>] (NJ); Fabia [15>] (NJ) Kombi; Kodiaq [17>] (NS7); Laura [04>13]; Octavia [13>] (5E3); Octavia [13>] (5E5) Kombi; Rapid [13>] (NH1) Spaceback; Rapid [13>] (NH3); Superb B6 [08>15] (3T4); Superb B8 [15>] (3V3); Superb B8 [15>] (3V5) Wagon; Yeti [09>] (5L7);

**SMART:** Forfour [04>07] (454); Forfour [14>] (453); Forfour [17>] (453) EV; Fortwo [07>14] (451) Cabrio; Fortwo [07>14] (451) Coupé; Fortwo [14>] (453) Coupé; Fortwo [15>] (453) Cabrio; Fortwo [16>] (453) EV Coupé;

## Multi-function display

**VOLKSWAGEN:** Bora | BR; Eos | BR; Golf | BR; Jetta | BR; New Beetle | BR; Scirocco | BR; Tiguan | BR; Beetle (Maggiolino) [11>] (5C1); Beetle (Maggiolino) [13>] (5C7) Cabriolet; Bora [06>13] (1K2); Eos [11>] (1F8); Golf VI [08>13] (5K1); Golf VI [09>13] (AJ5) Variant; Golf VI [09>14] (521) Plus; Golf VI [11>15] (517) Cabriolet; Jetta [10>] (162);

**LANCIA:** Delta [08>13] (181); Kappa [94>00]; Lybra [99>06]; Lybra [99>06] Station Wagon; Musa [04>]; Thesis [02>09]; Ypsilon [03>06]; Ypsilon [06>11];

**LEXUS:** NX 200t | BR; ES (V6) 200 [16>]; GS (L1) 200t [15>]; GS (L1) 350 [12>]; IS (E3) 200t [15>] Sedan; NX (Z1) 200t [14>]; RC (C1) 200t [15>]; RX (L2) 200t [15>]; RX (L2) 350 [15>];

**MASERATI:** GranTurismo [07>] (M145); GranTurismo [10>] (M145) Convertible;

**MERCEDES-BENZ:** C | BR; A [12>] (176); B [11>] (246); C [07>14] (204); C [07>14] (204) T; C [11>14] (204) Coupé; C [14>] (205); C [14>] (205) L; C [14>] (205) T; C [15>] (205) Coupé; C [16>] (205) Cabrio; CL [06>15] (216); CLA [13>] (117); CLA [15>] (117) Shooting Brake; CLS [11>] (218) Coupé; CLS [11>]



(218) Shooting Brake; E [09>15] (212); E [09>16] (207) Coupé;

**OPEL (GM):** Astra-F; Astra-J [09>15]; Astra-J [09>15] Station Wagon; Astra-J [12>15] Sedan; Astra-K [15>]; Astra-K [15>] Station Wagon; Cascada [13>]; Corsa-B [93>03]; Insignia-A [08>13] Hatchback; Insignia-A [08>13] Sedan; Insignia-A [08>13] Station Wagon; Insignia-A [13>16] Hatchback Facelift; Insignia-A [13>16] Sedan Facelift; Insignia-A [13>16] Station Wagon Facelift; Insignia-A [14>16] Country Tourer; Mokka [12>]; Tigra-A [94>99]; Zafira-C [12>] Tourer;

**RENAULT:** Twingo III [14>] (X07/BC);

**VOLVO:** S90 II [16>]; V90 II [16>]; XC90 I [03>14]; XC90 II [15>];

## LPG/Petrol injection

**FIAT:** 500X [15>] (334);

**JEEP:** Renegade [14>] (BU);

## Methane/Petrol injection

**AUDI:** A3 [12>] (8V1); A3 [12>] (8VA) Sportback;

**OPEL (GM):** Zafira-C [12>] Tourer;

**SEAT:** Leon [12>] (5F1); Leon [14>] (5F8) ST; Mii [12>] (KF1);

**SKODA:** Citigo [12>] (NF1); Octavia [13>] (5E3); Octavia [13>] (5E5) Kombi;

**VOLKSWAGEN:** Golf VII [12>] (5G1); Golf VII [14>] (BA5) Variant; Up! [11>] (121/122);

## Diesel injection

**PORSCHE:** Cayenne [10>] (92A/958) Diesel; Cayenne [12>] (92A/958) S Diesel; Panamera [11>] (970) Diesel;

**SEAT:** Altea [04>15] (5P1); Altea Freetrack [07>15] (5P8); Altea XL [06>15] (5P5); Ateca [16>] (KH); Ibiza [08>15] (6J1) Sportcoupé; Ibiza [08>15] (6J5); Ibiza [10>15] (6J8) ST; Leon [05>12] (1P1); Leon [12>] (5F1); Leon [12>] (5F5) SC; Leon [14>] (5F8) ST; Toledo [12>] (KG3);

**SKODA:** Kodiaq [17>] (NS7); Laura [04>13]; Octavia [04>13] (1Z3); Octavia [04>13] (1Z5) Kombi; Octavia [13>] (5E3); Octavia [13>] (5E5) Kombi; Praktik [07>15] (5J7); Rapid [13>] (NH1) Spaceback; Rapid [13>] (NH3); Superb B6 [08>15] (3T4); Superb B6

[09>15] (3T5) Kombi; Superb B8 [15>] (3V3); Superb B8 [15>] (3V5) Wagon; Yeti [09>] (5L7);

**SMART:** Fortwo [04>06] (450) Cabrio; Fortwo [04>06] (450) Coupé; Fortwo [07>14] (451) Cabrio; Fortwo [07>14] (451) Coupé; Smart [98>04] (450) Coupé; Smart [99>04] (450) Cabrio;

**SUZUKI:** Ignis [01>08] (RG/RM); Swift [04>10] (RS);

**VOLKSWAGEN:** Beetle (Maggiolino) [11>] (5C1); Beetle (Maggiolino) [13>] (5C7) Cabriolet; Caddy [10>] (2C/2K); Golf V [04>10] (1K5) Variant; Golf VI [08>13] (5K1); Golf VI [09>13] (AJ5) Variant; Golf VI [09>14] (521) Plus; Golf VI [11>15] (517) Cabriolet; Golf VII [12>] (5G1); Golf VII [14>] (BA5) Variant; Golf VII [15>] (AM1) Sportsvan; Jetta [05>10] (1K2);

**VOLVO:** S90 II [16>]; V90 II [16>]; XC90 II [15>];

## Tyre pressure

**FERRARI:** 599 GTB Fiorano [06>12] (F141); 599 GTO [10>12] (F141); 612 Scaglietti [04>07] (F137); 612 Scaglietti [07>11] (F137 MY);

**LEXUS:** LS 460 | BR; NX 200t | BR; RX 350 | BR; ES (V6) 200 [16>]; ES (V6) 250 [12>]; ES (V6) 300h [12>]; ES (V6) 350 [12>]; GS (L1) 200t [15>]; GS (L1) 250 [12>15]; GS (L1) 300h [13>]; GS (L1) 350 [12>]; GS (L1) 450h [12>]; GS (L1) F [15>]; HS (F1) 250h [09>]; IS (E3) 200t [15>] Sedan; IS (E3) 250 [13>15] Sedan; IS (E3) 300 [16>] Sedan; IS (E3) 300h [13>] Sedan; IS (E3) 350 [13>] Sedan; LFA (A1) [10>12]; LS (F4) 460 [07>]; LS (F4) 600h [07>]; LX (J2) 450d [16>];

**MASERATI:** GranTurismo [07>] (M145); GranTurismo [10>] (M145) Convertible; Quattroporte [04>07] (M139); Quattroporte [07>12] (M139 EV07);

**MERCEDES-BENZ:** AMG GT [15>] (190) Coupé; AMG GT [15>] (190) Roadster; C [14>] (205); C [14>] (205) L; C [14>] (205) T; C [15>] (205) Coupé; C [16>] (205) Cabrio; GLC [15>] (253); GLC [16>] (253) Coupé; S [13>] (222); S [13>] (222) L; S [14>] (217) Coupé; S [15>] (217) Cabrio; S [15>] (222) Maybach;

**SCION:** FR-S [12>] (N6); iM [15>] (E18);

**SMART:** Fortwo [07>14] (451) Cabrio; Fortwo [07>14] (451) Coupé;

**TOYOTA:** Prius | BR; 86 [12>] (N6); Alphard [16>] (H30); Aqua [11>] (P10) Hybrid; Aurion [12>] (V50); Auris [13>] (E18); Auris [13>] (E18) Wagon; Avalon IV [12>] (X40); Avalon IV [13>] (X40) Hybrid; Camry

[12>] (V5); Camry [12>] (V5) Hybrid; C-HR [17>] (NG/ZY); Corolla [13>] (E17/E18); Crown [13>] (S21); GT86 [13>] (N6); Highlander II [07>13] (U4);

## Hybrid battery system

**TOYOTA:** Prius [10>16] (ZVW) Plug-in;

## Front camera

**ALFA ROMEO:** Giulia [16>] (952);

**LEXUS:** RX 350 | BR; ES (V6) 200 [16>]; ES (V6) 250 [12>]; ES (V6) 300h [12>]; ES (V6) 350 [12>]; GS (L1) 200t [15>]; GS (L1) 300h [13>]; GS (L1) 350 [12>]; GS (L1) 450h [12>]; GS (L1) F [15>]; IS (E3) 200t [15>] Sedan; IS (E3) 300 [16>] Sedan; IS (E3) 300h [13>] Sedan; IS (E3) 350 [13>] Sedan; LX (J2) 450d [16>]; LX (J2) 570 [15>]; RX (L2) 200t [15>]; RX (L2) 350 [15>]; RX (L2) 450h [15>];

**NISSAN:** NV 400 [14>];

**OPEL (GM):** Movano B [14>];

**RENAULT:** Master 3 [14>];

**TOYOTA:** Hi-Lux | BR; Prius | BR; Avalon IV [12>] (X40); Avalon IV [13>] (X40) Hybrid; Camry [12>] (V5); Camry [12>] (V5) Hybrid; C-HR [17>] (NG/ZY);



Corolla [13>] (E17/E18); Fortuner [16>]; Highlander III [14>] (U5); Highlander III [14>] (U5) Hybrid; Hi-Lux [16>] Pick-Up; Hi-Lux [16>] SW4; Land Cruiser [07>] (J20); Prius [16>] (ZVW); Prius [17>] (ZVW) Plug-in; Prius Prime [17>] (ZVW) Plug-in; RAV4 [13>] (A4).

## Multifunction camera

**MERCEDES-BENZ:** C | BR; A [12>] (176); AMG GT [15>] (190) Coupé; AMG GT [15>] (190) Roadster; B [11>] (246); C [07>14] (204); C [07>14] (204) T; C [11>14] (204) Coupé; C [14>] (205); C [14>] (205) L; C [14>] (205) T; C [15>] (205) Coupé; C [16>] (205) Cabrio; CL [06>15] (216); CLA [13>] (117); CLA [15>] (117) Shooting Brake; CLS [11>] (218) Coupé; CLS [11>] (218) Shooting Brake; E [09>15] (212); E [09>16] (207) Coupé; E [09>16] (212) T; E [10>16] (207) Cabrio.

**SMART:** Forfour [14>] (453); Forfour [17>] (453) EV; Fortwo [14>] (453) Coupé; Fortwo [15>] (453) Cabrio; Fortwo [16>] (453) EV Coupé.

\* DASHBOARDS are currently available for IDC5 Windows (AXONE Nemo, AXONE 4, PC).



## END OF THE COMPATIBILITY OF TEXA DIAGNOSTIC SOFTWARE PROGRAMS WITH MICROSOFT WINDOWS XP AND WINDOWS VISTA OPERATING SYSTEMS.

Starting from June 2017, TEXA's diagnostic software programs can no longer be installed in the following operating systems: Windows XP, Windows Vista. In order to be able to continue using the extraordinary diagnostic functions guaranteed by the IDC5 software, you must have a PC with an updated operating system.

The operating systems that will continue to be supported by TEXA's diagnostic software programs are the following: Windows 7 sp1 32 Bit, Windows 7 sp1 64 Bit, Windows 8 32 Bit, Windows 8 64 Bit, Windows 8.1 32 Bit, Windows 8.1 64 Bit, Windows 10 32 Bit, Windows 10 64 Bit.

For further details on these functions and on their applicability to vehicles, visit:

[www.texa.com/coverage](http://www.texa.com/coverage)



# Extended coverage of makes - Version 65

## CARS AND LIGHT COMMERCIALS


ABARTH  
 ACURA  
 AGRALE  
 ALFA ROMEO  
 ASTON MARTIN  
 AUDI  
 AUTOBIANCHI  
 BMW  
 BRILLIANCE  
 BSI VEICOLI  
 BYD  
 CADILLAC  
 CHANGAN  
 CHERY  
 CHEVROLET  
 CHRYSLER  
 CITROEN  
 DACIA  
 DAEWOO  
 DAIHATSU  
 DODGE  
 DR  
 EFFA  
 FAW  
 FIAT  
 FORD  
 FREIGHTLINER  
 GAZ  
 GENESIS  
 GMC  
 GONOW  
 GREAT WALL  
 HAFEI  
 HOLDEN  
 HONDA  
 HUMMER  
 HYUNDAI  
 IKCO  
 INFINITI  
 INNOCENTI  
 ISUZU  
 IVECO  
 IVECO LATIN AMERICA  
 JAC MOTORS  
 JAGUAR  
 JEEP  
 KATAY  
 KIA  
 LADA  
 LANCIA  
 LAND ROVER  
 LDV  
 LEXUS  
 LOTUS  
 MAHINDRA  
 MARUTI  
 MAYBACH  
 MAZDA  
 MERCEDES-BENZ  
 MERCEDES-BENZ (BRASIL/ASIA  
 PACIFIC)  
 MG


MINI  
 MITSUBISHI  
 NISSAN  
 OPEL (GM)  
 PERODUA  
 PEUGEOT  
 PIAGGIO  
 PLYMOUTH  
 PORSCHE  
 RAVON  
 RENAULT  
 RENAULT SAMSUNG  
 ROVER  
 SAAB  
 SCION  
 SEAT  
 SKODA  
 SMART  
 SOLLERS FIAT  
 SPERANZA  
 SSANGYONG  
 SUBARU  
 SUZUKI  
 TATA  
 TOYOTA  
 UAZ  
 VAZ  
 VICTORIA GIOTTI  
 VOLKSWAGEN  
 VOLVO  
 WULING

## SUPERCAR

ALFA ROMEO  
 ASTON MARTIN  
 BENTLEY  
 CHEVROLET  
 DODGE  
 FERRARI  
 LAMBORGHINI  
 MASERATI  
 McLAREN  
 MORGAN  
 PAGANI  
 PORSCHE  
 ROLLS-ROYCE

## LEGEND









 Brands that offer updates in this version

 Brands that do not offer updates in this version

This document is strictly confidential. All copying, in part or in whole, is strictly forbidden without the prior authorisation of TEXA S.p.A. Future specifications, descriptions and appearances may vary with respect to this brochure. TEXA S.p.A. reserves the right to modify its products without prior notice.

## WARNING

The trademarks and logos of vehicle manufacturers in this document have been used exclusively for information purposes and are used to clarify the compatibility of TEXA products with the models of vehicles identified by the trademarks and logos. Because TEXA products and software are subject to continuous developments and updates, upon reading this document they may not be able to carry out the DIAGNOSTICS of all the models and electronic systems of each vehicle manufacturer mentioned within this document. References to the makes, models and electronic systems within this document must therefore be considered purely indicative and TEXA recommends to always check the list of the "Systems that can be diagnosed" of the product and/or software at TEXA authorized retailers before any purchase. **The images and the vehicle outlines within this document have been included for the sole purpose of making it easier to identify the vehicle category (car, truck, motorbike, etc.) for which the TEXA product and/or software is intended.** The data, descriptions and illustrations may change compared to those described in this document. TEXA S.p.A. reserves the right to make changes to its products without prior notice.

		
+39 0422 791311	texa.com	info.it@texa.com
		
facebook.com/texacom	twitter.com/texacom	youtube.com/texacom
		
instagram.com/texacom	linkedin.com/company/texa	plus.google.com/+TEXAcom



**COMPANY WITH  
 QUALITY SYSTEM  
 CERTIFIED BY DNV GL  
 = ISO 9001 =**

The BLUETOOTH brand is the property of Bluetooth SIG, Inc., U.S.A., and is used by TEXA S.p.A. under license.

Copyright TEXA S.p.A. - 10/2017 - Inglese

MADE IN ITALY 

